IADC Maintenance Committee Meeting

April 10th 2019





Topics

Springs for Anchor Winches

Require more details to assist with follow up

TDX-1250 Motor Decouple

- > Issue only reported from one rig
- > 1000010757-PIB released March 2016
- ➤ Shift limiting feature removed from production
- > Shift limiting feature to be removed during unit overhauls

TDX-1250 hub disengagement

- > Extensive testing done in-house, unable to replicate failure
- > 1000012113-PIN released Aug 2017
- > Torsional shock load and improper shaft to hub assembly
- Software update and DIT required

TDX-1250 Hydraulic IBOP's

- > Testing is a pain NOV engineering designing single ball valve option.
- ➤ Air operated IBOP can be shifted remotely
- Correctly testing new design dual ball valve IBOP.

G-series elevators

➤ PIB G-SERIES-180-PIB-001 explains limitations of elevators

© 2015 NOV | Proprietary and confidential.

Document Number: 100734228 Revision Number: Slide: 2